A portion of the North 1 of the Southwest 1 of Section 23, T23N, R19E W.M. Chelan County, Washington, ing portions of and being modified by the following documents: Lot 1 of Short Plat #1395, that boundary justment Short Plat #1780, and that boundary line agreement as filed in 1912 in Book 98 at Page 510 under iditor #43171, a portion of Parcel C contained in that deed as filed with the Chelan County Auditor's Office in book 944 at Page 1636, that parcel filed with the Chelan County Auditor's Office in Book 854 at Page 034 under iditor #8602180024 Tract 1 on Page 39 and the exception on the bottom of page 39, along with portions of other ircels recorded under the said Auditor no., described as follows:

Beginning at the Southwest corner of the said Section 23 as monumented by the BLM in 1990 with a brass p, thence along the West line of the said Section North 02°01'34" West 1350.09 feet to the South 1/16th corner the West line of the said Section 23 as also monumented by the BLM in 1990 with a brass cap, thence ontinuing along the said West line North 02°01'49" West 1348.93 feet to the West 1 corner of the said Section 23 monumented by the BLM in 1990 with a brass cap, thence South 79°11'37" East 1068.27 feet to a 3/4" pipe set the middle of Fairview Canyon County Road, thence South 70°36'44" East 3.04 feet to a 5/8" rebar set by ourt Order and recorded in Book 28 of Surveys at Pages 1 & 2 with the Chelan County Auditor's Office, thence ong the said Court Ordered line as shown on the said recorded survey North 79°05'02" East 26.79 feet to a ound 5/8" rebar, thence North 79°04'43" East 95.43 feet to a 5/8" rebar as shown on the said survey and the oint of beginning of this description, thence South 08°47'30" East 451.03 feet, thence South 88°19'41" West 1.15 feet to the Easterly R/W line of Fairview Canyon County Road as dedicated this plat 30.00 feet from enterline shown on those Short Plats recorded with the Chelan County Auditor's Office, Short Plat #2027 and hort Plat #2028, thence along the said Easterly R/W line South 46°02'04" East 17.74 feet to the P.C. of a curve ight, thence along the said curve to the right whose radius is 316.47 feet, 133.78 feet through a central angle f 24°13'12", thence continuing along the said Easterly R/W line South 21°48'52" East 154.40 feet to the P.C. of curve right, thence along the said curve to the right whose radius is 275.87 feet, 99.88 feet through a central ngle of 20°44'36" to the North line of that area created by boundary adjustment in Short Plat #1780 as recorded ith the Chelan County Auditor's Office in Book 898 at Page 464, thence along the Northeast and South lines of he said boundary adjustment area South 86°17'15" East 95.82 feet, thence South 42°53'37" East 87.02 feet. hence South 34°17'19" East 33.52 feet, thence South 44°14'27" West 66.53 feet, thence North 70°39'40" West 36.87 feet to the Easterly R/W line of Fairview Canyon County Road as dedicated this plat 30.00 feet from enterline, thence along the said R/W line South 01°10'30" West 9.47 feet to the South line of Lot 1 of Short Plat 1395, thence along the said South line South 70°40'35" East 498.05 feet, thence continuing along the said South ine South 65°21'50" East 27.35 feet, thence North 88°19'36" East 151.19 feet along the South line of the said Lot of Short Plat #1395 and along the South line of that parcel as recorded with the Chelan County Auditor's)ffice in that sale contract filed Book 854 at Page 34 being Exhibit "A" on page 39 being Tract 1, to the Southeast corner of the said Tract 1, thence along the East line of the said Tract 1 North 01°41'38" West 1090.35 eet to the Northeast corner of the said Tract 1, thence along the North line of the said Tract 1 South 88°16'45" Vest 29.94 feet, thence leaving the said North line North 01°43'15" West 11.08 feet to the that line established by Court Order previously cited in this legal description, thence along the said Court Ordered line South 38°48'45" West 22.30 feet, thence South 87°50'34" West 44.60 feet, thence South 87°19'44" West 54.76 feet, thence North 88°42'34" West 14.77 feet, thence South 87°01'17" West 62.77 feet, thence South 87°29'08" West 51.65 feet, thence North 89°52'17" West 72.56 feet, thence North 82°36'17" West 21.56 feet, thence North 54°05'26" West 6.16 feet, thence South 87°49'05" West 59.52 feet, thence South 87°23'40" West 58.50 feet, thence North 16°09'54" East 11.94 feet, thence South 89°18'49" West 197.35 feet, thence South 88°38'12" West 71.10 feet, thence South 79°03'55" West 41.44 feet to the point of beginning and the end of this description.

TIED 1991, FND STONE IN MONUMENT CASE SCALE NOT T PROPORTIONAL FIRM. POINT I" TO 1000' 11/4" 2645.81 2645.81 14 CASE S88°22'33"W S88°22'32"W (1326.31) 500 23 (EAST) 23 APPROX. LOCATION OF 1912 AGREEMENT 2649.88° S02°13'30"E LINE (2640°) 2632.88° SOI°37'49"[15. 2637.1 CALCULATED POSITION OF THAT STONE 24 AS FOUND ON THE 1945 MAP FROM THE FOUND IRON PIPES A & B AS SHOWN ON THE DETAIL (SEE PG 2 OF 3 THIS SVY). CALCULATED POSITION BY SECTION BREAKDOWN S63°51'26"E 22.60' CALC. 1/16th CORNER BY 5305.47 SECTION BREAKDOWN S88°38'57"W NOT TIE FIRM, R. MARKED FND BLM BC, TIED DEC. 1994 22 1327.04 2651.39 1327.04 PROJECT 362. 1348. S02°13'30"E 2724.05' AREA 1329.42 FND BLM BC ON N88°55'49"E PIPE, TIED JUNE 1992 34 05 1350.0 1356.0 FND MARKED STONE, 23 TIED 1989 23 1331.93 1331.92 N89°11'05"E FND BLM BC 26 2663.85 26 ON PIPE, TIED DEC. 27 1994 LEGA POSITION OF FOUND NAIL IN HOLE TIED 1990 -- POSSIBLE POSITION

POSITION OF FOUND NAIL IN HOLE TIED 1990 -- POSSIBLE POSITION OF THAT STONE BY THE 1912 AGREEMENT SURVEY. THE 1945 SURVEY SHOWS "STONE NOT FND". REPASS MAP SHOWS RR SPIKE BY AGREEMENT SW CORNER NE 1/4 SW 1/4 ALSO USED FOR 1/16th CORNER SURVEYS FILED SW CORNER NE 1/4 SW 1/4 ALSO USED FOR 1/16th CORNER SURVEYS FILED BK 16, PG 34 AND BK 24, PG 53 AND SS 1653 BK SP-5, PG 61. FND NAIL BK 16, PG 34 AND BK 24, PG 53 AND SS 1653 BK SP-5, PG 61. FND NAIL TO CALC. 1/16th CORNER BY SECTION BREAKDOWN S39°39'20"E 45.14"

A portion of the North 1 being portions of and being adjustment Short Plat #1780, Auditor #43171, a portion of P

Well SITE

lat Residence

DATE OF TEST: 5/6/93

STATIC LEVEL: 31'

TESTED BY MIKE MICHAEL

DEPTH OF WELL:

691

| TIME | DEPTH TO WATER | PUMPING RATE | REMARKS |
|----------|----------------------------------|-----------------|--|
| 9:00 am | 31' | 36GPM | CLEAR |
| 9:15 | 67' | и | ıı e |
| 9:30 | PULLED AIR THROTTLED VALVE DOWN | 35GPM | ıı e |
| 9:45 | PULLED AIR | 34GPM | II . |
| 10:00 | THROTTLED DOWN STILL PULLING AIR | 33.4GPM | " |
| 10:30 | THROTTLED DOWN | 32.8GPM | u |
| 11:00 | STABILIZED | 31.3GPM | п |
| 11:30 | 67' | u , | n variable de la constant de la cons |
| 11:50 | 67' | u (/ dec | " |
| 12:25 pm | 67' | ii A jac | u |
| 12:55 | 67' | n . | |
| 1:15 | 67' | " // 13 | an in the second se |
| | | | SHUT PUMP DOWN WELL WILL PRODUCE 31.3 GPM |